

Gagemaker T050 | Trapezoidal Thread Contact Points | Pitch 2 $\frac{1}{2}$

The millimetre pitch diameter of machined parts with trapezoidal thread forms is checked using these contact points. For the majority of gauges, two are needed.



Specifications

Pitch

Details

2 $\frac{1}{2}$ mm

