

Gagemaker T144 | $7 \hat{A}^\circ$ X 45 \hat{A}° Buttress Series Contact Points | Pitch 4

The pitch diameter of machined parts with 7° X 45° Buttress thread forms is checked using these contact points. For the majority of gauges, two are needed.

×

Specifications	Details
Pitch	4

