

Gagemaker T105 | UN Series (60° V) Threads | Pitch 5 $\frac{1}{2}$

With 60° "V" thread forms, these contact points are used to inspect the pitch diameter of machined parts. For the majority of gauges, two are needed.



Specifications

Pitch

Details

5 $\frac{1}{2}$

