

Gagemaker T072 | UN Series (60° V) Threads | Pitch 8

With 60° "V" thread forms, these contact points are used to inspect the pitch diameter of machined parts. For the majority of gauges, two are needed.



Specifications

Details

Pitch

8

