

Gagemaker T437 | 7Ű X 45Ű Buttress Series Contact Points | Pitch 1ż

The pitch diameter of machined parts with 7° X 45° Buttress thread forms is checked using these contact points. For the majority of gauges, two are needed.

×

Specifications	Details
Pitch	1¼

×