

#### Gagemaker T144 | 7° X 45° Buttress Series Contact Points | Pitch 4

The pitch diameter of machined parts with 7° X 45° Buttress thread forms is checked using these contact points. For the majority of gauges, two are needed.



#### Specifications

#### Details

Pitch

4

