

Gagemaker T050 | 7° X 45° Buttress Series Contact Points | Pitch 12

The pitch diameter of machined parts with 7° X 45° Buttress thread forms is checked using these contact points. For the majority of gauges, two are needed.



Specifications

Details

Pitch

12

