

Gagemaker T032 | 7° X 45° Buttress Series Contact Points | Pitch 16 & 18

The pitch diameter of machined parts with 7° X 45° Buttress thread forms is checked using these contact points. For the majority of gauges, two are needed.



Specifications

Details

Pitch

16 & 18

